

Message

From: Bury, Carolyn [/O=EXCHANGELABS/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=DE91ECB9B8C044A4BF4C350615AE3633-CBURY]
Sent: 5/29/2019 1:45:04 PM
To: Chris Parks [cparks@iwmconsult.com]; jbian@amphenol-aao.com
CC: Brad Gentry [bgentry@iwmconsult.com]; Neal, Conor [Neal.Conor@epa.gov]; Sundar, Bhooma [sundar.bhooma@epa.gov]; Caudill, Motria [caudill.motria@epa.gov]
Subject: RE: Confidential: Draft Results [Ex. 6 Personal Privacy (PP)]

Thanks Chris.
 Carolyn

From: Chris Parks <cparks@iwmconsult.com>
Sent: Wednesday, May 29, 2019 8:10 AM
To: Bury, Carolyn <bury.carolyn@epa.gov>; jbian@amphenol-aao.com
Cc: Brad Gentry <bgentry@iwmconsult.com>; Neal, Conor <Neal.Conor@epa.gov>; Sundar, Bhooma <sundar.bhooma@epa.gov>; Caudill, Motria <caudill.motria@epa.gov>
Subject: Confidential: Draft Results [Ex. 6 Personal Privacy (PP)]

Carolyn,

Good morning. I wanted to pass along the Draft Results for [Ex. 6 Personal Privacy (PP)] This is the residence to the west of [Ex. 6 Personal Privacy (PP)]
 [Ex. 6 Personal Privacy (PP)] A sewer cleanout was not located on this residence. We were able to collect samples from the cellar [Ex. 6 Personal Privacy (PP)] I was told by the resident that the cellar floor was dirt, however, upon arrival, and inspection, it was a rough concrete pour. Unfortunately, we did not have a sub-slab sample point to sample from. However, several portions of the concrete walls in the cellar had deteriorated and are now dirt.

Regardless, all indoor air results were well below screening levels and we do not feel any additional actions are necessary on this residence.

Please let us know if you have any questions.

Thank you,
 Chris



Christopher D. Parks, LPG
 Senior Project Manager
 7428 Rockville Road
 Indianapolis, IN 46214
 Direct: (317) 968-9260
 Mobile: (317) 847-2600
 Office: (317) 347-1111 x 127
 Fax: (317) 347-9326